

# Field Termination Plug User Guide

**1**

Copper Foil Tape  
30mm  
10mm

**2**

Boot  
Cable

**3**

S/FTP or U/FTP.F/UTP

**4**

Copper Foil Tape

**5**

**6**

5-8mm Max.

**7**

Cut 2  
Cut 1  
0.2mm Max.

**8**

Align

**9 Hand screwing**

1 Close

**10**

1 Grip  
2 Screw

**Legend**

1	2	3	4	5	6	7	8
W-G	G	W-O	BL	W-BL	O	W-BR	BR

Pin assignment T568A

1	2	3	4	5	6	7	8
W-O	O	W-G	BL	W-BL	G	W-BR	BR

Pin assignment T568B

**11**

3.0mm Min.

	Solid	Stranded	Cable (O.D.)
C6 <sub>A</sub>	23~26AWG	23~26AWG	6.0~7.5mm

	Solid	Stranded	Cable (O.D.)
C8	22~24AWG	22~24AWG	7.0~8.5mm